

## Procédure R13026

### **SP13-10**

MODIFICATION OF I-SHIFT TRANSMISSION INTERLOCK PARAMETERS ON OBD13 WITH WHEELCHAIRLIFT

A transmission reprogramming is necessary in order to correct and interlock issue between the wheelchair lift system and the I-shift transmission

Validate transmission software part number in TSP:

MSW TECU= 22190392.

TECU - 3.1.0

Main Software

22190392 SOFTWARE,MSW, TECU, TEA2+

30IJP0

P+ ODS PREVOST PROD 1 KOLA

c. Then using Prosit, check MID. MID check result must indicate the same software number.