

Pour la version française, se référer au retrofit production 13024 (CORROSION BLOQUEUR PORTE ÉVAPORATEUR)

SP13-18 Corrosion on Evaporator Door Stopper

March 2013

Context : Possibility of galvanic corrosion between the aluminium door and the stainless steel evaporator door retaining mechanism (2800226);

Demo vehicles affected in service, see notifications of SP13-18 in SAP.

On evaporator door, replace **2800226 QTY 1** (if needed, use *BOLT 5001745* , *WASHER 500321*)

The back of the part must be painted to avoid GALVANIC CORROSION

