

Local Campaign Request Form

Rev3_March 2013

Request #

Payer

Bulletin

Other Reference

NYCT Campaign# ...

To be filled by Requester

Title

Replace the 4 Stressproof steel door studs with the new Hex door studs

Customer (s) involved

NYCT

Comments

This campaign replace Campaign SP12-316, previous solution did not fix the issue, Engineering develop a new stud with new procedure

Ref to procedure

Supplied by Engineering



Pièce jointe



Pièce jointe



Pièce jointe

Time Allocated (hr)

3hrs per coach= \$345.00

Parts involved

280913 (4):\$19.83*4= \$79.32
5001877 (8)\$3.57*8=\$28.56
500958 (12):\$0.84*12= \$10.08
Total: \$117.96 Per vehicles

Causal p/n

281252

Est. Cost per vehicle (at selling price)

\$462.96



Pièce jointe



Pièce jointe



Pièce jointe

Qty of vehicles involved

90 X3 commuter at NYCT

Total cost of campaign (cad)

\$41,666.40

List of equipments

NYCT 90 X3 Commuter

Type of Info ?

 Pièce jointe	 Pièce jointe	 Pièce jointe
--	--	--

- ☒ Please keep bulletin and notification internal (SP-type of bulletin)
- ☐ Please make sure procedure is publically available on our websites... (WB)

Comments

 Pièce jointe	 Pièce jointe	 Pièce jointe
--	--	--

To be filled by Warranty

Fail Code	18.01			
Defect Code	09			
System Condition				
Supplier Recovery				
Part Disposition				
Comments	Toujours pas capable d'éditer les 3 champs ci-dessus. System condition B			
	<table><tr><td> Pièce jointe</td><td> Pièce jointe</td><td> Pièce jointe</td></tr></table>	 Pièce jointe	 Pièce jointe	 Pièce jointe
 Pièce jointe	 Pièce jointe	 Pièce jointe		

To be filled by Tech Pub

Publication #	sp13-312			
VBC Bulletin #	n/a			
Cost Approval Date	2013-04-02			
Notif Create Date	2013-04-04			
Comment				
	<table><tr><td> Pièce jointe</td><td> Pièce jointe</td><td> Pièce jointe</td></tr></table>	 Pièce jointe	 Pièce jointe	 Pièce jointe
 Pièce jointe	 Pièce jointe	 Pièce jointe		