

Subject Health Check Error Message and Diagnostic Report During Safety Recall DLC - Front Passenger Airbag Inflator Module		Market USA
Service Category Vehicle Interior	Section Supplemental Restraint Systems	
Applicability Certain Models		

APPLICABLE VEHICLES

2002-2003


SC430

CONDITION

The technical instructions for Safety Recall DLC (Front Passenger Airbag Inflator Module) require a Techstream Health Check and then a Diagnostic Report (Customer Friendly Health Check.)

Health Check Error

During the Health Check, a TIS Access Error (S309-10) dialog box may be displayed for certain 2002-2003MY SC 430 vehicles.

Diagnostic Report

The serial number checker application displays an error stating a Diagnostic Report record within the last 36 hours cannot be found.




Subject Health Check Error Message and Diagnostic Report During Safety Recall DLC - Front Passenger Airbag Inflator Module	Market USA
Applicability	
Certain Models	

RECOMMENDATIONS


Health Check Error

If the error message dialog box appears, click “Continue” and proceed with the Safety Recall’s technical instructions.



Diagnostic Report

Create a Diagnostic Report by clicking the ‘Diagnostic Report’ button. Once the report is generated, the serial number checker application can be used.



LINK REFERENCES

This Tech Tip does not contain any link references