

Subject		Market
Noise while driving from windshield molding or loose windshield molding		USA
Service Category	Section	
Vehicle Exterior	Exterior Panels/Trim	
Applicability		
2011-2014 Scion tC		

APPLICABLE VEHICLES

2011-2014

tC

CONDITION

Some customers may complain of a loose windshield molding or noise while driving as a result of a loose molding.

RECOMMENDATIONS

- This issue is currently under investigation.
- Please create a TAS case and contact the Technical Assistance System (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with the diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with the TAS Product Engineer.
- When creating a TAS case, use the following case coding to ensure it is directed to the Body group:
Vehicle Exterior + Exterior Panels/Trim + Exterior Trim/Moldings + Noise-wind noise/whistle

LINK REFERENCES

This Tech Tip does not contain any link references