

Subject

Installation of Rubber Body Plugs During PDS

Market

USA

Service Category

General

Section

Pre-Delivery Service

Applicability

Avalon - Avalon HV

APPLICABLE VEHICLES

2013	Avalon	2013	Avalon HV
------	--------	------	-----------

CONDITION

2013 Avalon vehicles are equipped with 2 front and 2 rear torque box holes located in the lower section of the body.

RECOMMENDATIONS

The oval-shaped rubber body plugs should be installed in the 4 torque box holes during Pre-Delivery Service (PDS).

Installation of the rubber body plugs reduces cabin noise and prevents moisture from entering the body.

See photos below that show the front/rear locations of the torque box holes with and without the rubber body plugs installed:

Figure 1. Front Tie-Down Location - Before Installation



Figure 2. Front Tie-Down Location - After Installation




Figure 3. Rear Tie-Down Location - Before Installation



Figure 4. Rear Tie-Down Location - After Installation



Subject

Installation of Rubber Body Plugs During PDS

Market

USA

Applicability

Avalon - Avalon HV

LINK REFERENCES

1. [T-SB-0213-12: 2013 Avalon Pre-Delivery Service \(PDS\)](#)