



Bulletin No.: PI1142


Date: Dec-2013

Service Bulletin


PRELIMINARY INFORMATION


Subject: Front Floor Console Extension Side Panel Change

Models: 2014 Chevrolet Impala
Vehicles Built Prior to November 1, 2013



The purpose of this PI is to inform the technician that when replacing the front floor console extension side panels, the new panels come with an additional clip tower, shown in the illustration above, that needs to be modified for vehicles built prior to the date listed above.





Cut the clip tower using a pair of wire cutters as shown in the illustration above.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION