T-SB-0146-10

Rev2

June 9, 2010



## Brief Engine Knock/Rattle Noise at Cold Startup (1AR/2AR)

Service

Category Engine/Hybrid System

Section Engine Mechanical Market USA



## **Applicability**

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2010 – 2011	Camry	Engine(s): 2AR Transmission(s): 6MT, 6AT VDS(s): BF3EK
2009 – 2011	Highlander	Engine(s): 1AR Transmission(s): 6AT VDS(s): DA41A, ZA3EH
2009 – 2011	RAV4	Engine(s): 2AR Transmission(s): 4AT VDS(s): BF31V, BF32V, BF33V, BF34V, BF35V, BF4DV, DF4DV, EF4DV, JF4DV, KF4DV, RF4DV, WF4DV, XF4DV, YF4DV, ZF31V, ZF32V, ZF33V, ZF34V, ZF35V, ZF4DV
2011	Sienna	Engine(s): 1AR Transmission(s): 6AT VDS(s): KA3DC
2009 – 2011	Venza	Engine(s): 1AR Transmission(s): 6AT VDS(s): BA3BB, BE11A, ZA3BB, ZE11A

## **OBSOLETE NOTICE**

March 15, 2013: This bulletin is now obsolete. Please see T-SB-0041-13.