

Subject:

Market:

Capacitive Sensor Sensitivity Setting for Navigation System (Navigation Receiver Type/Radio and Display Type) and Air Conditioning System

USA

Service Category:

Audio/Visual/Telematics

Section:

Navigation/Multi Info Display

Applicability:

2013 Avalon/ Avalon HV

APPLICABLE VEHICLES

2013	Avalon	2013	Avalon HV
------	--------	------	-----------

CONDITION

Some customers may feel sensitivity of control buttons of Navigation system and air conditioning system is low (unresponsive) or high (responds before touching the sensor).

Note: Tech Tip is issued for your convenience due to the potential difficulty of finding this information in repair manual.

RECOMMENDATIONS

Please see the attached links from the repair manual for details on how to adjust sensitivity setting.

LINK REFERENCES

- [NAVIGATION / MULTI INFO DISPLAY: NAVIGATION SYSTEM \(for Navigation Receiver Type\): OPERATION CHECK; 2013 MY Avalon \[10/2012 -\]](#)
- [NAVIGATION / MULTI INFO DISPLAY: NAVIGATION SYSTEM \(for Radio and Display Type\): OPERATION CHECK; 2013 MY Avalon \[10/2012 -\]](#)
- [HEATING / AIR CONDITIONING: AIR CONDITIONING SYSTEM: SYSTEM DESCRIPTION; 2013 MY Avalon \[10/2012 -\]](#)