



Service Bulletin

PRELIMINARY INFORMATION

Subject: Pre Delivery Inspection (PDI) - License Plate Packaged with Wrong Bolt

Models: 2013 Buick Encore
2013 Chevrolet Trax (Canada Only)
Built Prior to February 6, 2013

Condition/Concern

The front license package may contain incorrect bolts.



Note: Incorrect bolts have a round head as shown in the illustration above.



Note: Correct bolts have a hex-head as shown in the illustration above.

Recommendation/Instructions

Replace incorrect bolts with the following part number.

Parts Information

Part Number	Description	Qty
11588712	Bolt	2

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION