



Service Bulletin

PRELIMINARY INFORMATION

Subject: Flex Fuel Sensor and Bracket Part Change

Models: 2013 Chevrolet Impala

Due to a running change in production where 2012 flex fuel sensors and brackets were installed on some 2013 vehicles, the following service information is being provided.

Vehicles Built Prior to February 26, 2013

These vehicles were built with a 2013 flex fuel sensor and bracket. If a flex fuel sensor requires replacement, the bracket must also be replaced using the part numbers listed below.

Vehicles Built After February 26, 2013

These vehicles were built with a 2012 flex fuel sensor and bracket. If a flex fuel sensor requires replacement, the sensor only needs to be replaced with the part number listed below.

Parts Information

Part Number	Description
13577379	SENSOR, FLEX FUEL
20862563	BRACKET, FLEX FUEL

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION