



Service Bulletin

PRELIMINARY INFORMATION

Subject: P0341 DTC Set in History

Models: 2014 Chevrolet Impala, Malibu
Equipped with 2.5L Engine (RPO LKW)

Condition/Concern

Some technicians may find DTC P0341 set in history without setting a Malfunction Indicator Light (MIL).

Recommendation/Instructions

If the DTC is in history and did not turn on the Malfunction Indicator Light (MIL), the code should be cleared and the vehicle returned to the customer. Do not replace any parts. If the Malfunction Indicator Light (MIL) was on, refer to SI for diagnostics.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4069929	Electrical Controls – Labor Only (To Clear DTC P0341)	0.2 hr

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION