

Sound: Poor audio quality after software update of sound amplifier

Topic number	LI82.62-P-055715
Version	1
Design group	82.62 Loudspeakers, amplifiers, antennas
Date	03-05-2013
Validity	Model series 207.3 with sound amplifier (code 810)
Reason for change	
Reason for block	

Complaint:

Poor audio quality from all audio sources. The complaint occurs only after a software update of the sound amplifier with XENTRY version 01/2013.

Cause:

Software of "SOUND System" sound amplifier (N40/3) with version 08/15.04

Remedy:

The software of the sound amplifier must be flashed again. To do this, generate an XSF ticket from XENTRY.

Symptoms
Communication/information / Entertainment / Audio / Tone setting malfunction
Communication/information / Entertainment / Audio / Poor audio quality

Validity		
Vehicle	Engine	Transmission
207.302	*	*
207.303	*	*
207.322	*	*
207.323	*	*
207.326	*	*
207.334	*	*
207.336	*	*
207.347	*	*
207.348	*	*
207.355	*	*
207.356	*	*
207.357	*	*
207.359	*	*

XENTRY

207.365	*	*
207.372	*	*
207.373	*	*
207.388	*	*