



Countries: CANADA, UNITED STATES

Availability: ISIS, Fleet!SIS

Major System: ENGINES

Current Language: English

Other Languages: NONE

Viewed: 3938

Document ID: IK1200739

Revision: 6

Created: 3/16/2012

Last Modified: 11/21/2013

Author: Daniel Modesto

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 303	 78

Title: SPN 27 FMI 7 EGRP does not agree with commanded position

Applies To: 2010 Emissions MaxxForce 11L and 13L

DESCRIPTION

- ECM shows an active SPN 27 FMI 7.

NOTE: This concern is currently under investigation and the contents of this article are subject to change at a later date!

SYMPTOMS

- Check engine light is on.

POSSIBLE DIAGNOSTIC TROUBLE CODES

DTC	SPN	FMI	MODULE	DESCRIPTION
	27	7	ECM	EGRP does not agree with Commanded Position

PARTS INFORMATION

- 7092735C93 KIT, EGR VALVE

RESOLUTION

- Replace the EGR valve

Warranty Claim

No Diagnostic time can be applied to the warranty claim for this repair since you are directed to replace the EGR valve if the 27-7 code is present. ONLY the allowed SRT for the EGR valve replacement can be applied to the warranty claim.

Hide Details

Feedback Information

Viewed: 3937

Helpful: 303

Not Helpful: 78

No Feedback Found

Copyright © 2013 Navistar, Inc.