



|                          |                          |                       |                |
|--------------------------|--------------------------|-----------------------|----------------|
| <b>Countries:</b>        | CANADA,<br>UNITED STATES | <b>Document ID:</b>   | IK1600183      |
| <b>Availability:</b>     | ISIS, FleetISIS          | <b>Revision:</b>      | 3              |
| <b>Major System:</b>     | CAB / SLEEPER /<br>HOOD  | <b>Created:</b>       | 5/9/2013       |
| <b>Current Language:</b> | English                  | <b>Last Modified:</b> | 11/18/2013     |
| <b>Other Languages:</b>  | NONE                     | <b>Author:</b>        | Jim Restemayer |
| <b>Viewed:</b>           | 1114                     |                       |                |

[Less Info](#)

Hide Details

#### Coding Information

| Copy Link | Copy Relative Link | Bookmark                              | Add to Favorites | Print | Provide Feedback | Helpful | Not Helpful |
|-----------|--------------------|---------------------------------------|------------------|-------|------------------|---------|-------------|
|           |                    | <br><a href="#">View My Bookmarks</a> |                  |       |                  | <br>10  | <br>1       |

**Title: Offensive Odors Inside Cabin**

**Applies To: Post 2010 ProStar**

## DESCRIPTION

Driver complaint of offensive odors in the cab.

## TOOLS REQUIRED

General hand tools  
1/4 inch drill bit  
Drill

## PARTS INFORMATION

Cowl Tray Kit : P/N 2511806C91

## REPAIR PROCEDURE

Click on the following items:

[Diagnostic Flow Chart](#)

[Cowl Tray Installation Instructions.docx.pdf](#)

## OTHER RESOURCES

Click on the following items:

[Exhaust Leak Troubleshooting for 2007](#)

[Exhaust Leak Troubleshooting for 2010 Emission](#)

[PDOC Clamp](#)

Click Here for: [Cowl Tray to Cab Seal Installation Procedure](#)

Click Here for: [Exhaust Manifold Ring Seal Removal / Installation](#)

Click Here for: [Exhaust Manifold Gasket Removal and Installation Procedure](#)

### Labor Information

A40-13665 Cowl Tray, Replace 0.7 Hrs

All claims for G-13665 activity must be submitted by 31 October 2013 coded to warranty code 40.

 Hide Details

#### Feedback Information

Viewed: 1113

Helpful: 10

Not Helpful: 1

| Staff ID | Client ID | Comments                                                                                                                                                        | Created Date           |
|----------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|
|          | DY35478   | You received the following feedback From: dy35478 - Steve Ziegler Email Address: Job Classification: SA003, Salesperson Dealer: SELKING INTERNATIONAL Feedback: | 11/20/2013 12:09:23 PM |

Copyright © 2013 Navistar, Inc.