



No.: 13 TS-7
March 1, 2013

TO: Service Locations

FROM: Service Operations

SUBJECT: **GHG14 CPC4 Vehicle Speed Sensor Code SPN 84/FMI 6**

ISSUE

Diagnostic code SPN 84/FMI 6 Vehicle Speed Sensor (VSS) anti-tamper detection via Antilock Brake System (ABS) vehicle speed comparison may set during shutdown of the engine system.

No lamps will illuminate and the code will be inactive.

REQUIRED ACTION

The code is inactive because it occurs at shutdown. Review the extended data record number #3 "Physical Data." If engine rpm is reported at less than 500 rpm, no action is required. If the code is active, diagnosis and repair will be required.

REPAIR PROCEDURE

No repair action is required if the code is inactive and engine rpm is less than 500 rpm. If the code is active, follow the diagnostic steps detailed in the DDC-SVC-MAN-0084 manual, found in Power Service Literature.

CONTACT INFORMATION

Please contact the Detroit™ Customer Support Center at 800-445-1980 or email csc@daimler.com if you have any questions.