

Description of Revisions: *This service bulletin replaces the version dated January 2013. It now lists all service bulletins published before April 1, 2013.*

Group 00, General Information

SB No.	Date	Service Bulletin Title
00-2	Feb08	Service Publications Price List
00-3	Feb06	Washing Delivered Vehicles to Reduce Road Salt Corrosion
00-5	Oct08	Tips for Using ServiceLit in ServicePro
00-6	Dec08	New Hazard Type Used in Service Literature
00-7	Apr09	Aluminum and Stainless Steel Cleaning and Polishing
00-8	Aug12	Routing and Clipping Tips for Extending School Bus Life

Group 01, Engine

SB No.	Date	Service Bulletin Title
01-1	Dec09	Dealer Input on EPA10 Engine Issues
01-2	Dec07	EPA07 MBE900 Engine Oil Dipstick Markings
01-3	Nov08	Adjusting Cummins ISB PTO Engine Load
01-4	Apr09	Belt Rattle on Cummins EPA07 Engines with Dual A/C Compressors

Group 20, Engine Cooling/Radiator

SB No.	Date	Service Bulletin Title
20-1	Sep05	Auxiliary Heater Switch Does Not Hold
20-2	Jul08	Changing of Air Fitting Type to Fix Engine Fan Control Air Leaks
20-3	Nov08	Use and Maintenance Guidelines for Extended-Life (OAT and NOAT) Coolants
20-4	Nov08	Use and Maintenance Guidelines for Fully Formulated Conventional Coolants
20-5	Oct10	Borg Warner (Kysor) Fan Clutch Nuts
20-6	Jun11	Surge Tank Leaks
20-7	Oct11	Interference Between the Upper Radiator Hose and Engine Hose Clamps
20-8	Apr12	Kysor Fan Clutch Sticking

Group 26, Transmission

SB No.	Date	Service Bulletin Title
26-2	Jul07	Fretting Corrosion on SmartShift™ Wiring
26-3	Mar08	Allison Transmission Fluid Specification

Group 31, Frame and Frame Components

SB No.	Date	Service Bulletin Title
31-1	Dec10	AirLiner Six-Piece Bolted Service Crossmember
31-2	Nov12	Huck-Spin 2 Changeover

Thomas Built Buses Service Bulletin

> Saf-T-Liner C2

Group 32, Suspension

SB No.	Date	Service Bulletin Title
32-1	Oct07	AMU Norgren Double-Check Valve Does Not Seal Completely
32-2	Sep10	AirLiner™ Suspension Air-Spring Bag Misalignment Troubleshooting

Group 33, Front Axle

SB No.	Date	Service Bulletin Title
33-1	Nov05	Tie-Rod and Drag-Link Ball-Stud Cover Deterioration

Group 35, Rear Axle

SB No.	Date	Service Bulletin Title
35-1	Feb12	Lubricating the Wheel Bearings, Rear Drive Axles

Group 42, Brakes

SB No.	Date	Service Bulletin Title
42-1	May06	Automatic Slack Adjuster Adjustment Caution
42-2	Jan08	Reservoir Internal/External Check Valve
42-3	Jan10	Air Management Unit (AMU) Replacement
42-4	Aug10	Air Line and Hose Rubbing

Group 46, Steering

SB No.	Date	Service Bulletin Title
46-1	Jul10	Adjustable Steering Column Release Pedal
46-2	May09	TRW Steering Column Tilt and Telescope Lock Adjustments

Group 49, Exhaust

SB No.	Date	Service Bulletin Title
49-2	Feb08	EPA07 Aftertreatment Device Visor Label
49-3	Mar09	Diesel Particulate Filter (DPF) Status Light On, EPA07 Engines
49-4	Sep12	Gentech DEF Coolant Flow Solenoid, Testing and Replacement
49-5	Feb13	DEF Gauge Reading Incorrectly
49-6	May12	DEF and Coolant Line and Fitting Leaks

Group 54, Electrical, Instruments, and Controls

SB No.	Date	Service Bulletin Title
54-1	Sep04	Using the Correct Port Cable for the Data Link Adapter
54-2	Jul10	Electrical Terminal Protection
54-3	Sep05	Caterpillar C7 Auto High Idle
54-4	Oct05	Battery Drain Overlay Harness
54-6	Sep05	Power Outlet Polarity Reversed
54-7	May07	ICU/3X Display of "Page Two" Fault Codes
54-9	Sep11	Unintended Wiper Cycling

SB No.	Date	Service Bulletin Title
54-10	Mar09	Replacing Battery Drawer Slides
54-11	Apr09	Water in Fuel Indicator Programming
54-12	Nov11	Troubleshooting Tips for ServiceLink Programming Issues
54-14	Feb11	Condensation and Possible Water Entry Points in Headlamp Assemblies
54-15	Feb11	New Headlamp Turn/Park/DRL Bulb Socket
54-16	Jan12	Chassis Module Replacement
54-17	Aug11	Instrument Panel and Gauge Lens Cover Cleaning
54-18	Nov12	Vehicle Starts in Pretrip Mode with Vandalock Active

Group 60, Cab

SB No.	Date	Service Bulletin Title
60-2	Mar08	Dash Cracks Around MV-3 Brake Valve

Group 83, Heater and Air Conditioner

SB No.	Date	Service Bulletin Title
83-1	Aug05	Use Only Approved Refrigerants
83-2	Oct06	A/C System Receiver-Drier Replacement Guidelines

Canceled Service Bulletins

Canceled Service Bulletins Since May 2007

SB No.	Canceled Date	Service Bulletin Title	Reason Code (see list below)
00-4	Dec08	Base Warranty Change for aged Vehicles	A
26-1	Apr08	ATF Fluid Specification	B
41-1	Jan12	Half-Round U-Joints, New Tightening Procedure	A
47-1	Jan10	Davco Fuel Pro 382 and Diesel Pro 232/233 Fuel/Water Separator Testing	A
49-1	Mar08	EPA07 MBE900 Regeneration Problem	B
60-1	May07	Incorrect Cab Mounts	A

A = Added to appropriate manual(s).

B = Information is obsolete.