

Measure no.

US 53528266-01

Subject

Fault code memory entry 0x21F960, throttle valve

Status date (mm/dd/yy)

1/23/13

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

1/23/13

Created by

Rainer Wanninger

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K48

Engine

6-ZYL

Body**Production period (from/to)**

(mm/dd/yy)

8/31/10 / 3/11/12

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

Complaint

Engine warning light lights up when the vehicle is in motion. Fault 0x21F960 throttle valve 1

"Comparison fault adapted values" is stored in the fault code memory.

Cause

Software error

Measure

Program the DME with integration level K001-12-08-500

Cause**Fault location**

13/61 Electronic control unit

Fault type**Fault place****Repair Task**

Program/encode

Special Clearance

No

Area

Powertrain

Fault code**Progman / DIS / ISTA / ISTA/P****System****State****Version**