



SI B51 21 11  
Body Equipment

February 2013  
Technical Service

This Service Information bulletin supersedes SI B51 21 11 **dated June 2011**.

**NEW** designates changes to this revision

#### SUBJECT

**Noises from the Glove Compartment Door**

#### MODEL

F10

Produced from November 30, 2009 to April 29, 2011

#### SITUATION

When vehicle is in motion, a grating or creaking noise may be heard from the glove compartment area.

#### CAUSE

The coating on the centering ribs of the glove compartment door has worn off.

#### PROCEDURE

Refer to the attachment and remove both centering ribs.

#### **NEW** WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty as applicable.

**Defect Code:**                   **51 16 09 39 00**

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
51 99 000	3 FRU	Work time to perform the repair procedure (Main work)
or		
51 99 000	1 FRU	Work time to perform the repair procedure (Plus work – vehicle is already in the workshop)

#### ATTACHMENTS

view PDF attachment [B512111 Attachment](#).

[ Copyright © 2013 BMW of North America, LLC ]