



SI B51 31 11
Body Equipment

February 2013
Technical Service

This Service Information bulletin supersedes SI B51 31 11 **dated September 2011.**

SUBJECT

Wind Whistle Noise from the Exterior Rearview Mirror

MODEL

F25 produced from August 31, 2010 to July 14, 2011

SITUATION

A whistling wind noise can be heard from either the left or right exterior rearview mirror, especially when traveling at highway speeds.

CAUSE

An excessive gap exists between the mirror base and acoustic triangular sealing gasket.

PROCEDURE

NEW Refer to the attachment.

PARTS INFORMATION

Part Number	Description	Quantity
51 33 7 205 594	Triangle seal right	One as needed
51 33 7 205 593	Triangle seal left	One as needed

WARRANTY INFORMATION

NEW Covered under the terms of the BMW New Vehicle/SAV Limited Warranty.

Defect Code: 51 16 00 39 00

Labor Operation:	Labor Allowance:	Description:
51 16 000	Refer to KSD	Remove and installing or replacing mirror on left or right door

Labor operation code 51 16 000 is a main labor operation. If you are using a main labor code for another repair, use the plus code labor operation 51 16 500 instead.

ATTACHMENTS

view PDF attachment [B513111 Attachment](#).

[Copyright © 2013 BMW of North America, LLC]