

March 2013 Technical Service

SUBJECT

N54 Engine: Fuel Pressure Control Test Plan Error

MODEL F01	
F02	
E82	
E88	
E89	
E90	
E92	
E93	
E60	
E61	

SITUATION

E71

Two errors may be encountered when performing Test Plan B1214_DI6KDR – Fuel Pressure Control with the current version of ISTA/D:

- On the last step when the diagnosis code is displayed, the test plan may state to replace the fuel low-pressure sensor and that a Bosch sensor will need to be installed.
- The right side of the test plan screen will provide two incorrect pictures and statements describing the fuel low-pressure sensors.

All of the statements related to the identification of the fuel low-pressure sensor are incorrect. Replace the fuel low-pressure sensor that is identified in ETK only after entering the vehicle identification number. Do not replace the metal fuel line with this pressure sensor.

This error will be corrected in ISTA/D 3.39.0.

WARRANTY INFORMATION

Not applicable.

[Copyright ©2013 BMW of North America, Inc.]