



SI B51 07 13
Body Equipment

March 2013
Technical Service

SUBJECT

Water Leaks into Cargo Area

MODEL

F25

Produced from August 31, 2010 to March 30, 2012

SITUATION

Water leaks into the cargo area and corrodes/damages electrical components.

Note: In most cases, the customer is not aware of any water in the lower compartments of the cargo area, but complains of an electrical malfunction or failure, as a result of water intrusion.

CAUSE

- Body seam sealer application inadequate
- The rear sunroof drains are dislodged.

PROCEDURE

Refer to the attachment.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty.

Use the following defect code for eligible repairs on applicable F25 vehicles to repair the “cause” of water ingress, as stated above, into the cargo area.

Defect Code:	51 71 91 48 00	
Labor Operation:	Labor Allowance:	Description:
Refer to KSD2	Refer to KSD2	Claim the applicable labor operation(s) that correspond to the work performed to correct the issue outlined in this Service Information bulletin
and/or		
Sublet Code 3	See sublet reimbursement	Reimbursement for repairs to the body panel seam and, if applicable, consequential body corrosion repairs as necessary

ATTACHMENTS

View PDF attachment [B510713 Attachment.](#)

[Copyright ©2013 BMW of North America, Inc.]