

Measure no.

US 50561128-02

Subject

Display "02 08 rb" in K16 instrument cluster

Status date (mm/dd/yy)

3/18/13

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

3/18/13

Created by

Carsten Gruetzmacher

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K16

Engine

1-ZYL

Body**Production period (from/to)**

(mm/dd/yy)

/

Comment on production period**Feedback (all cases relating to****measure up to) (mm/dd/yy)****Complaint**

Display shows an unrecognized character combination.

Cause

- Instrument cluster battery (CR 24 Lithium) spent or
- Instrument cluster battery (CR 24 Lithium) has contact problems in the battery compartment

Measure

Check the battery in the instrument cluster and replace if necessary.

To do this, see chapter 7 of the Owner's Handbook, "Instrument cluster - replacing the instrument cluster battery"

Complaint

	Fault location	Fault type	Fault place
▶	Displaying	Malfunction	
▶	62/11 Driver information display	Display: Fault, incomplete	

Cause

	#	Fault location	Fault type	Fault place
▶	1	62/11 Instrument cluster		

Repair Task

Special Clearance

Area

No

Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System

State

Version

© 2002-2013 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.