

Measure no.

US 53804253-01

Subject

K46/11 and K42 side stands

Status date (mm/dd/yy)

3/8/13

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

3/8/13

Created by

Thomas Eichholz

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K42 K46/11

Engine

4-ZYL

Body**Production period (from/to)**

(mm/dd/yy)

/

Comment on production period**Feedback (all cases relating to measure up to) (mm/dd/yy)****Complaint**

New vehicles are being delivered to the dealership fitted with different side stands

Cause

As of 12/04/2012, a component change was introduced in series production – side stands are now anodized in silver instead of in black.

Measure

No action is required before the vehicle is handed over to the customer.

As of the following vehicle identification numbers, silver-anodized side stands are fitted in vehicles.

VIN / MODEL

ZL17721 / S 1000 RR (K46/11)

ZC96668 / HP4 (K42)

Complaint

Fault location	Fault type	Fault place
46/53 Side stand	Radiation	

Cause

Fault location

Fault type

Fault place

1	46/53 Side stand	Paint defect	
	Repair Task	Special Clearance	Area
	No action	No	Chassis and Suspension

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
---------------	--------------	----------------

© 2002-2013 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.