

Measure no.

US 53826242-01

Subject

Swinging arm gaiter to gearbox is split or collapsed

Status date (mm/dd/yy)

3/13/13

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

3/13/13

Created by

Peter Loertzing

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K50

Engine**Body****Production period (from/to)**

(mm/dd/yy)

/

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

Complaint

The gaiter between the swinging arm and the gearbox is split or collapsed (see attached photos).

Cause

The swinging arm gaiter material is insufficient.

Measure

If a swinging arm gaiter on the gearbox side of a vehicle is split or collapsed, the gaiter must be replaced. The latest version of this component is significantly improved and no longer tends to collapse.

Complaint

	Fault location	Fault type	Fault place	Fault conditions
1	33/17 Rear wheel swinging arm gaiter	Ding		While driving

Cause

#	Fault location	Fault type	Fault place
1	33/17 Rear wheel swinging arm gaiter	Leak: Grease	
	Repair Task	Special Clearance	Area
	Replace	No	Chassis and Suspension

Fault code

Progman / DIS / ISTA / ISTA/P

System

State

Version

© 2002-2013 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.

