

Measure no.

US 53834526-01

Subject

Incorrect anti-theft alarm (DWA) operating instructions

Status date (mm/dd/yy)

3/15/13

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

3/15/13

Created by

Bernhard Kistler

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K50

Engine**Body****Production period (from/to)**

(mm/dd/yy)

/

Comment on production period**Feedback (all cases relating to****measure up to) (mm/dd/yy)****Complaint**

DWA 6 operating instructions were supplied with the new R 1200 GS (K50) that have DWA option X603.

These are not the correct instructions for this new model.

Cause

Due to a release error, the operating instructions for DWA 6 were supplied with the vehicle.

Measure

Remove the DWA 6 operating instructions as part of the pre-delivery inspection. The correct description of the DWA is an integral part of the motorcycle operating instructions.

Important note: There is no DWA remote control for the K50.

Complaint**Fault location**

01/40 OWNER'S
HANDBOOK / ON-BOARD
LITERATURE

Fault type

Wrong component

Fault place**Cause****# Fault location****Fault type****Fault place**

1 01/40 OWNER'S Wrong component
HANDBOOK / ON-BOARD
LITERATURE

Repair Task	Special Clearance	Area
Other tasks	No	Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
---------------	--------------	----------------

© 2002-2013 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.