

Measure no.

US 54585509-01

Subject

Instrument cluster fault codes

Status date (mm/dd/yy)

8/13/13

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

8/13/13

Created by

Martin Bumba

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K48

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to****measure up to) (mm/dd/yy)**

/

Complaint

During K 1600 GT/GTL pre-delivery check or the running-in check, the faults "26000 impermissible operating mode" and "B7F609 coding error" are read in the instrument cluster.

Cause

Due to the assembly process at the factory, the entry is generated in the fault memory and was not correctly cleared on the assembly line.

Measure

The fault code memory entry does not cause a fault in the instrument cluster and is to be deleted.

Complaint

	Fault location	Fault type	Fault place
1	62/11 Instrument cluster	Software: Old version	

Cause

#	Fault location	Fault type	Fault place
1	62/11 Instrument cluster	Software error	
	Repair Task	Special Clearance	Area
		No	Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
---------------	--------------	----------------
