

Revisions to this document are noted
by a stripe in the left-hand margin

2012FA03, Rev. C
September, 2013
Page 1 of 6

SUBJECT: H 40/50 EP™ Dual Power Inverter Module 2 (DPIM2) Field Action

MODELS AFFECTED: Dual Power Inverter Module 2 (DPIM2)

VOCATIONS AFFECTED: Transit buses equipped with H 40/50 EP™

SERIAL NUMBERS AFFECTED: S/N 7210010001 through S/N 7210011222

Introduction:

Allison Transmission, Inc. has identified the need for removing and replacing some Dual Power Inverter Modules (DPIM2), part number P/N 29548557. The serial numbers affected are S/N 7210010001 through S/N 7210011222. Allison Transmission, Inc. is replacing the DPIM2s listed serial number range at no cost, regardless of vehicle age or mileage. In order to participate in this Global Customer Satisfaction Field Action (FA), all repair orders must be opened prior to May 1, 2014.

DPIM2s built after S/N 7210011222 are not affected by this Field Action.

Distributors should contact the Allison H 40/50 EP™ customers in your Area of Responsibility to schedule the DPIM2 Field Action activity. Attached is a copy of the Customer Letter.

Service Procedure:



WARNING: Before beginning any repair on the H 40 EP System™, perform the Electrical Disconnect Verification Procedure found in the H 40/50 EP™ Service Manual SM3602.

Allison Transmission, Inc. has identified the listed operations for this Field Action. Allison H 40/50 EP™ trained technicians are to perform this Field Action at authorized H 40/50 EP™ service outlets only. As soon as the vehicle has been received, proceed as follows: Authorization Required Prior to Conducting DPIM2 Replacement. If Authorization Number is not obtained you do not have authorization to continue with DPIM2 replacement. Distributors and Dealers must log on to the Allison Extranet (<https://sap.allisontransmission.com/extranet>) to the Field Action Authorization channel located under the Warranty channel. Obtain Authorization Number prior to performing the DPIM2 replacement. When in the Field Action channel, select the hyperlink for 2012FA03 and then complete the fields displayed. This authorization number must be included in the claim narrative for claim consideration.

A Field Action Authorization Number is required prior to replacing the DPIM2. If the Field Action Authorization Number is not obtained, do not continue with the replacement.

If you are unable to obtain an authorization number, and you believe the DPIM2 qualifies for the Field Action based on the serial number range, contact the Allison Technical Assistance Center (TAC) at 800-252-5283 or 317-242-0700.

Ordering a DPIM2 that Fails, in the Field Action S/N Range:

If a DPIM2 in the affected S/N range fails before the Field Action is completed on that bus, order a DPIM2 using the following as a guide:

- Order replacement DPIM2, P/N 29548557 through normal parts ordering process.
- File claim for the failed DPIM2 as Claim Type 1 (CT01) - warranty or Claim Type 2 (CT02) - ETC, as applicable.
- Return failed DPIM2 via AWAARE RMA process.
- If Claim Type 1 or Claim Type 2 do not apply, contact Allison TAC for instructions on ordering a replacement DPIM2.

Ordering a DPIM2 on a Pro-Active Basis for this Field Action:

Contact the Allison Technical Assistance Center (TAC) at 1-800-252-5283 or email allison.tac@allisontransmission.com to order a replacement DPIM2 for this Field Action only. The Allison Technical Assistance Center will provide a DPIM2 at no cost. When contacting TAC, the information below must be provided.

- DPIM2 Serial Number
- Bus Number
- Vehicle Identification Number (VIN)
- Mileage
- Distributor Branch Location
- Shipping Information

Replace the DPIM2 as outlined in H 40/50 EP™ Service Manual, SM3602.



NOTE: The DPIM2 AC Cable Flange Gaskets, P/N 29550771 are one-time use only. These gaskets must be replaced when installing the replacement DPIM2.

Core Submittal:

- Create a Return Transaction in SAP for the DPIM2 core.
- Only one Return Transaction may be created per DPIM2 core.
- Use part number, DPIM2CM for the Return Transaction in SAP.
- SAP will generate a Return Material Authorization (RMA).
- Include the following information in the Serial Number text field of the Return Transaction in SAP:
 - DPIM2 Serial Number (returned and installed)
 - Field Action Authorization Number
 - Customer
 - Bus Number

- Vehicle Identification Number (VIN)
- Mileage
- Arens RMA #5547
- Securely affix a legible copy of the on-line SAP-generated Return Material Authorization form to the DPIM2. It is suggested that a clear plastic shipping envelope be wired to one of the mounting bolt holes to protect it.

DPIM2 cores returned that have oil/water intrusion due to missing shipping plugs and/or covers will be deemed unusable. DPIM2 cores that are deemed unusable due to improper shipping will be invoiced to the distributor at the value of \$39,066.00.

The returned DPIM2s are to be sent to the address listed below before the claim is filed:

Allison Transmission, Inc.
C/O Arens Controls Company, LLC
Attn: DPIM2, 2012FA03 Return
3602 N. Kennicott Ave.
Arlington Heights, IL 60004

Core Freight Criteria:

Allison Transmission, Inc. will pay the core freight charges for the return of DPIM2 cores when the following conditions are met:

- Carrier Information: Effective August 1, 2013, FedEx Freight® is the exclusive carrier for all DPIM2 Field Action Truck shipments.
- Call FedEx Freight® for all DPIM2 core shipments less than 20,000 lbs. and less than 75% of the trailer capacity. All freight must be called in and ready by noon (your local time) to ensure same day pickup.
 - For all pick-ups in USA, please call 1-866-393-4585 and state "FedEx Freight® ECONOMY SERVICE"
 - For all pick-ups in Canada and Mexico, please call 1-866-393-4685 and state "FedEx Freight® ECONOMY SERVICE"
- State the number of pieces of freight, approximate weight, destination city on your bill of lading.
- The freight terms are prepaid and the body of the bill of lading should state; FedEx Freight® ECONOMY SERVICE Third Party Bill Freight To:

Allison Transmission, Inc.
Attn: Data 2 Logistics
P.O. Box 61050
Fort Myers, FL 33906

(Billing Address only; DO NOT ship to this location)



NOTE: Allison Transmission, Inc. has strict metrics in place to not only ensure the material is delivered to manufacturing plants and customers on time, as well as free of any loss or damage. Contact the Allison Transportation Department 48 hours in advance for routing instructions on all shipments greater than 20,000 lbs., or if the freight will occupy more than 75% of a trailer. Contact the Allison Transportation Department at 317-821-5110, 317-821-5106, 317-821-5107, or 317-821-5112 for any transportation concerns, including freight damage and loss claims.



NOTE: Any costs incurred by Allison Transmission, Inc. as a result of noncompliance of the above routings will be debited to your account.

- Third party billing labels are available from RR Donnelly, and can be ordered through Allison's Publications link at www.allisontransmission.com, reference publication number ST2240EN.
- For Canada and all other international inbound shipments, include the broker's name and the statement Return of U.S. Goods, Allison Transmission, Inc. Shipment on the invoice, bill of lading, and packing list.
- Use FedEx Trade Networks, 734-229-4000 for Canadian customs clearance.
- Use Ceva Logistics 1-614-489-5238 or fax 1-281-372-7402 for customs clearance of imports from non-North American countries.
- All international inbound shipments must include a customs invoice detailing the incoterms FCA (origin name). Description: Dual Power Inverter Module 2 CM, P/N 29548557, DPIM2 Core cost \$39,066.00, customs clearance by broker's name stated above, quantity shipped, serial number of each unit, weight per piece, tariff classification, total weight, and country of origin USA.
- Attach Declaration of Foreign Shipper (DFS).
- DPIM2 cores must be shipped from an Allison Transmission, Inc. recognized distributor, branch location, or direct dealer in the Continental U.S., Hawaii, Canada, or other designated locations acceptable to Allison Transmission, Inc. Allison Transmission, Inc. will pay all freight charges and any duties and taxes once the goods arrive in the United States.
- DPIM2 cores must meet core criteria and submittal requirements.
- DPIM2 cores must be shipped via freight carriers recommended by Allison Transmission, Inc., as stated above.
- The shipping destination on the bill of lading must identify the cores as being shipped to Allison Transmission Core Processing Center.

Claim Submittal:

Claims must be submitted against the removed DPIM2 serial number. Replacement serial number must be included in the "Replacement Transmission Serial Number" field. Any repairs not prescribed in this Field Action (FA) are to be claimed on a separate claim.

Allison Service Outlets must use the published Allison Transmission Labor Time Guide for work performed. The following labor operations will be required to complete the Field Action. Any additional parts or labor costs deemed necessary to complete this Field Action must be described in detail in the claim narrative. Failure to follow the instruction on this Field Action will result in the claim not being paid.

Claim Type	CT04*
Special Activity Code	2012FA03
Primary Failed Part	29548557
Complaint Code	AT02
Failure Code	CC03
Field Action Authorization Number	Provided from Extranet, must be listed in claim narrative

Service Replacement Indicator	ReTran®
* If the DPIM2 fails on a bus before the Field Action has been completed on that bus, replace DPIM2 with a new DPIM2, P/N 29548557 and file the claim as a Claim Type1, CT01, or Claim Type 2, CT02, (as applicable) with Special Activity Indicator 2012FA03	

	DPIM2 Failed	DPIM2 Not Failed	Special Instructions*
DPIM2 within FA S/N Range and still in 2 year warranty	CT01	CT04	CT01 – utilize normal parts ordering process. CT04 – order DPIM2 replacement through Allison TAC.
DPIM2 within FA S/N range with ETC, less than 5 years and more than 2 years	CT02	CT04	CT02 – utilize normal parts ordering process. CT04 – order DPIM2 replacement through Allison TAC.
DPIM2 within FA S/N greater than 2 years without ETC	**	CT04	CT04 – order DPIM2 replacement through Allison TAC.
DPIM2 within FA S/N range with ETC, greater than 5 years	N/A	CT04	CT04 – order DPIM2 replacement through Allison TAC.
DPIM2 outside FA S/N range, less than 2 years	CT01	N/A	CT01 – utilize normal parts ordering process.
* Claims must reference Special Activity Indicator 2012FA03 for replacement DPIM2s in affected Field Action serial number range			
** Contact Allison TAC for instructions			

Product Code 71		
Labor Operation Code	Labor Hours	Labor Operation
94000040	4.0 hours	Remove and Replace DPIM2 (MCI D Series Coach)
94000030	3.0 hours	Remove and Replace DPIM2 (All Other Transit Buses)
00096501	1.0 hours	Reflash entire system with updated SID
00096400	0.5 hours	Test Drive, Check and Clear Codes

H 40/50 EP™ High Voltage Shutdown Verification Procedure may not be added to the remove and replace operation.

Applicable Net Items	List (US)
DPIM2 Handling Fee*	\$1,000.00
* DPIM2 Handling Fee includes preparing the DPIM2 for shipment (ie: caps, plugs and crate).	

Contact Information:

If you have questions concerning this Global Customer Satisfaction initiative, please contact:

Allison Transmission, Inc.
Attn: H 40/50 EP Service Group
P.O. Box 894, Mail Code M5B
Indianapolis, IN 46222
1-800-252-5283

DECLARATION OF FOREIGN SHIPPER

I, _____, declare that the articles herein specified are, to the best of my knowledge and belief, the growth, produce, or manufacture of the UNITED STATES. They were exported from the port of _____ on or about UNKNOWN. They are returned without having been advanced in value or improved in condition by any process or manufacture.

Invoice No. _____

Part No.: _____

Quantity: _____

Description: _____

Unit Price: _____

Total Value: _____

Shipper: _____

Signature: _____

Title: _____

Date: _____