



Countries:	CANADA, UNITED STATES	Document ID:	IK1200559
Availability:	ISIS, Bus ISIS, FleetISIS	Revision:	2
Major System:	ENGINES	Created:	12/14/2010
Current Language:	English	Last Modified:	8/26/2013
Other Languages:	Français , Español ,	Author:	Joe Christopher
Viewed:	719		

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 92	Not Helpful 110
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	-------------------------------

Title: Failed ECM Programming When Using DLC Automatic Upgrade

Applies To: All MaxxForce Engines

DESCRIPTION

DLC Automatic Upgrade fails to complete programming.

RESOLUTION

If a dialog box displays a failed message during programming while using DLC Automatic Upgrade, follow the next steps.

1. Disconnect interface cable and cycle ignition key.
2. Reconnect interface cable try to recover using DLC Automatic Upgrade
3. If unsuccessful, reprogram the ECM with NETS while selecting blank/new module option.
4. If NETS fails to complete the programming process ***Do not replace module.***
5. Open case a file and contact Vehicle Programming for further assistance.

Hide Details

Feedback Information

Viewed:	718
Helpful:	92
Not Helpful:	110
No Feedback Found	