

Fault message in display - Right rear turn signal light inoperative

Topic number	LI82.10-P-053604
Version	3
Design group	82.10 Exterior lights
Date	07-08-2013
Validity	W and C 204
Reason for change	Updated part numbers
Reason for block	

Complaint:

Fault message in display - Right rear turn signal light inoperative

Cause:

Contamination on the circuit board surface due to flux in combination with moisture.

This can lead to a brief failure of the flashing light sequence.

Remedy:

Replace rear lamp

Symptoms
Overall vehicle / Lighting / Exterior lights / Turn signal/hazard warning lights / Turn signal/hazard warning lights indicator lamp / Turn signal indicator / Nonfunctional
Overall vehicle / Lighting / Exterior lights / Turn signal/hazard warning lights / Turn signal lights / Nonfunctional

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A 204 906 06 03			Left rear lamp	1	as of model year 802	X	
A 204 906 07 03			Right rear lamp	1	as of model year 802	X	
A 204 906 89 02			Left rear lamp	1	Bi-xenon, up to model year 801	X	
A 204 906 90 02			Right rear lamp	1	Bi-xenon, up to model year 801	X	
A 204 906 83 02			Left rear lamp	1	Without bi-xenon, up to model year 801	X	
A 204 906 84 02			Right rear lamp	1	Without bi-xenon, up to model year 801	X	

Work units				
Op. no.	Operation text	Time	Damage code	Note
			82202 52	Taillamp turn signal light

Validity		
Vehicle	Engine	Transmission
204.000	*	*
204.001	*	*
204.002	*	*
204.003	*	*
204.006	*	*
204.007	*	*
204.008	*	*
204.022	*	*
204.023	*	*
204.025	*	*
204.031	*	*
204.041	*	*
204.044	*	*
204.045	*	*
204.046	*	*
204.047	*	*
204.048	*	*
204.049	*	*
204.052	*	*
204.054	*	*
204.055	*	*
204.056	*	*
204.057	*	*
204.065	*	*
204.077	*	*
204.080	*	*
204.081	*	*
204.082	*	*
204.085	*	*
204.087	*	*
204.088	*	*
204.089	*	*
204.092	*	*
204.302	*	*
204.303	*	*

XENTRY

204.331	*	*
204.347	*	*
204.349	*	*
204.357	*	*
204.377	*	*
204.388	*	*