

Side air vents in instrument panel reflected in side windows

Topic number	LI83.10-P-049809
Version	2
Design group	83.10 Ventilation
Date	07-22-2013
Validity	Model series 212
Reason for change	Different parts as of facelift.
Reason for block	

Complaint:

The side air vents in the instrument panel may be reflected in the side windows in sunlight.

Attachments	
File	Designation
4.JPG	Reflection of side air vent in side window

Cause:

Silver colored side air vents

Remedy:

Replace the silver air vents with black air vents.

Prior to facelift: A 212 830 29 54 9116

: A 212 830 30 54 9116

After facelift : A 212 830 01 00

: A 212 830 02 00

NOTE: This repair is NOT covered under Warranty.

Symptoms
Body / Air conditioning / Heater / Center air vent does not close
Body / Interior equipment / Instrument panel / Surface discolored
Body / Interior equipment / Interior trim / Discolored

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A 212 830 29 54 9116			Air vent, left	1	black		X
A 212 830 30 54 9116			Air vent, right	1	black		X
A2128300100			Air vent, left	1	black		X

A2128300200		Air vent, right	1	black		X
-------------	--	-----------------	---	-------	--	---

Work units				
Op. no.	Operation text	Time	Damage code	Note
			83A02 ZZ	Damage type ZZ
			83N02 ZZ	Damage type ZZ

WIS-References			
Document number	Title	Note	Allocation
AR83.10-P-4740ew	Remove/install side air vent		Remedy

Validity		
Vehicle	Engine	Transmission
212.002	*	*
212.003	*	*
212.005	*	*
212.020	*	*
212.024	*	*
212.025	*	*
212.047	*	*
212.048	*	*
212.052	*	*
212.053	*	*
212.054	*	*
212.056	*	*
212.057	*	*
212.072	*	*
212.077	*	*
212.087	*	*
212.089	*	*
212.090	*	*
212.147	*	*
212.154	*	*
212.202	*	*
212.203	*	*
212.205	*	*
212.220	*	*
212.224	*	*
212.225	*	*

XENTRY

212.247	*	*
212.248	*	*
212.254	*	*
212.256	*	*
212.257	*	*
212.272	*	*
212.277	*	*
212.287	*	*
212.289	*	*