



Countries:
Availability:
Major System: ENGINES
Current Language: English
Other Languages: NONE
Viewed: 40

Document ID: IK1200891
Revision: 0
Created: 2/27/2013
Last Modified: 3/12/2013
Author: Brian Reeves

[Less Info](#)

Hide Details

Coding Information

| | | | | | | | |
|----------------------|-------------------------------|--|-----------------------------|------------------|-----------------------------|-------------------------|-----------------------------|
| Copy Link | Copy Relative Link | Bookmark View My Bookmarks | Add to Favorites | Print | Provide Feedback | Helpful 1 | Not Helpful 0 |
|----------------------|-------------------------------|--|-----------------------------|------------------|-----------------------------|-------------------------|-----------------------------|

Title: MX7 Service Engines with the aftermarket Thermal Management Valve

Applies To: MX7 Service Engines: 7080062C92, 7080063C92, 7091736C92

DESCRIPTION

When replacing a MF7 Service Engine that has an aftermarket Thermal Management Valve, part number 1898911C2, currently installed. It is required to apply dielectric grease (NYE NYOGEL®760G) to the TMV connectors.

For additional information on the MF7 Thermal Managent Valve Kit, refer to iKNOW artical IK1200719.

Hide Details

Feedback Information

| |
|--|
| Viewed: 39 Helpful: 1 Not Helpful: 0 |
| No Feedback Found |

Copyright © 2013 Navistar, Inc.