

Technical Service Bulletin

SUBJECT:			No:	TSB-13-11-001
OIL PUMP CHAIN GUIDE ELIMINATED – SERVICE MANUAL REVISION			DATE:	January, 2013
			MODE	L: See below
CIRCULATE TO:	[] GENERAL MANAGER	[X] PARTS MANAGER		[X]TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[X] WARRANTY PROCESSOR		[] SALES MANAGER

PURPOSE

The oil pump chain guide was eliminated in 2.0 liter (4B11) non-turbo engines effective with July 1, 2012 production. This TSB provides updated service manual information.

AFFECTED VEHICLES

2013 Lancer with 2.0L engine (except Ralliart)

2013 Lancer Sportback with 2.0L engine

2013 Outlander Sport (RVR)

AFFECTED SERVICE MANUALS

2013 Lancer/Lancer Sportback: Group 11B Engine Overhaul > Oil Pump Chain > Removal & Installation 2013 Outlander Sport: Group 11B Engine Overhaul > Oil Pump Chain > Removal & Installation


Continued

Copyright 2013, Mitsubishi Motors North America, Inc.

(3938)

Make the indicated changes to:

2013 Lancer/Lancer Sportback: Group 11B Engine Overhaul > Oil Pump Chain > Removal & Installation 2013 Outlander Sport: Group 11B Engine Overhaul > Oil Pump Chain > Removal & Installation



- MB991346: Top cover wrench
- MB991883: Flywheel Stopper

• MD998718: Rear Oil Seal Installer