

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: February 1, 2013
TO: Mitsubishi Motors Parts Managers
Mitsubishi Motors Service Managers
RE: 2013 Outlander Sport /RVR TPMS Sensor - Temporary Production (REVISED)
TIN NO. TIN-13-42A-001

AFFECTED VEHICLES: Certain 2013 Outlander Sport/RVR

This document replaces TIN-12-42A-001 issued October, 2012, to provide updated information about the use of temporary production and service parts being extended due to continued supply issues. Individual changes are not identified.

PURPOSE

Due to a supply issue with the “snap-in” type Tire Pressure Monitoring System (TPMS) sensor, subject vehicles are temporarily being built using the 2012 “clamp in” type sensor. This change will affect production and service parts until the supply issue is resolved. An owner’s manual addendum card reflecting this change has been placed in the glove box of affected vehicles.

The TPMS sensor type can be easily identified by the valve stem.



This change is effective with the following vehicles:

- 18” alloy wheels: DE007466 built 10/18/2012
- 16” alloy wheels: DE007527 built 10/17/2012
- 16” steel wheels: DE007484 built 10/18/2012

This change will result in p/n 4250C276 being temporarily superseded to p/n 4250B975 in the service parts system. Once p/n 4250C276 becomes available, the supersession will be broken, allowing supply of both part numbers. If a replacement sensor is required, install p/n 4250B975. If a customer comments about the cosmetic difference, advise them the original specification sensor can be installed, at no cost to them, when inventory becomes available.

There is no affect to diagnostic or registration procedures. Both sensor types use the same diagnostic trouble codes and registration steps.