

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: February 6, 2013

TO: Mitsubishi Motors Sales Managers
Mitsubishi Motors Parts Managers
Mitsubishi Motors Service Managers

RE: 2013 Outlander, Lancer and Lancer Sportback – Front License Plate
Hardware Eliminated - REVISED

TIN NO. TIN-13-51-001


This notice supersedes TIN-12-42A-002, issued November, 2012 to change the minimum length of recommended M6 fasteners. Changes are italicized and indicated by ◀

AFFECTED VEHICLES: 2013 Outlander beginning December, 2012
2013 Lancer/Lancer Sportback beginning September, 2012

PURPOSE

Affected vehicles are no longer shipped with front license plate hardware (rubber nut and bolt package). Dealers are asked to use self-tapping screws for mounting the front license plate. License plates should be installed in the locations indicated by dimples in the front fascia. Dealers should use locally sourced, non-corroding, M6 fasteners, 20mm to 25 mm long. **Fasteners should be installed using hand tools only.** ◀

Please do not submit any claims for missing front license plate hardware.



Rear license plate mounting screws will continue to be shipped in the glove box.