



NUMBER: 23-018-13

GROUP: Body

DATE: May 09, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-032. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Windshield Wiper Vibration

OVERVIEW:

This bulletin involves removing and replacing the wiper module linkage bolts.

MODELS:

2013 (JK) Wrangler

NOTE: This bulletin applies to vehicles built on or after January 23, 2013 (MDH0123XX) and on or before January 24, 2013 (MDH0124XX).

SYMPTOM/CONDITION:

Windshield wiper blade vibration.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
2 (AR)	06104370AA	Wiper Module Linkage, Bolt

REPAIR PROCEDURE:

1. Remove and replace the wiper module linkage bolts (Fig. 1) with p/n 06104370AA. Refer to the detailed service information in DealerCONNECT> TechCONNECT> Service Information tab> 08-Electrical> 8R - Wiper/Washers> LINKAGE, Wiper Arm> Removal/Installation.




Fig. 1 Front Wiper Module

1 - Wiper Module Linkage Bolts

2 - Wiper Module

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
23-43-56-93	Remove and Replace Wiper Module Linkage Bolts (2 - Semi-Skilled)	0.3 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------