

9002900 05/01/2013 MY12-13 LC, LD, LX, WK, LX

GPOP - Issue Review System

Part Number: 1YR88DX9A\$, 1YR89DX9A\$, 1YR88LU5A\$, 1YR89LU5A\$, 1YR88LC5A\$,
1YR89LC5A\$, 05035243AA, 05035242AA

Part Description: Switch-Padedle Down Audio LT.
Switch-Paddle Up Audio RT.

Issue Description: When traveling over bumpy roads, a high pitched ringing/bell sound may come from the left or right paddle switch's in the steering wheel. If this noise is heard, replace both Left and Right Paddle switch.
