



NUMBER: 08-045-13

GROUP: Electrical

DATE: June 21, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-043. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

The Electronic Vehicle Information Center EVIC Does Not Function Properly

OVERVIEW:

This bulletin involves installing the correct EVIC switch in the steering wheel to allow the EVIC to function properly.

MODELS:

2012 JK Wrangler (International Only)

SYMPTOM/CONDITION:

The EVIC may not function as designed.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
1	56046405AB	Switch, Steering Wheel EVIC

REPAIR PROCEDURE:

Replace the EVIC steering wheel switch. Follow the detailed service procedures available in DealerCONNECT/TECHCONNECT, Refer To 8 - Electrical - 8M - Message Center > Switch, EVIC Control > Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount

08-80-82-95	Switch, Steering Wheel EVIC (2- Skilled)	0.3 Hrs.
-------------	---	----------

FAILURE CODE:

ZZ	Service Action
----	----------------