



NUMBER: 08-003-13

GROUP: Electrical

DATE: January 15, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Clock In The Radio Loses Time

OVERVIEW:

This bulletin involves replacing the Wireless Control Module (WCM)/Sentry Key Remote Entry Module (SKREEM).

MODELS:

- | | | |
|-------------|------|----------|
| 2009 - 2012 | (JK) | Wrangler |
| 2009 - 2012 | (KK) | Liberty |
| 2009 - 2011 | (KA) | Nitro |

SYMPTOM/CONDITION:

Customer may experience a condition where the clock will lose over one minute a month.

DIAGNOSIS:

If the customer describes the symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1 AR	68209969AA	SCREEM/WCM, With remote start (XBM sales code)
1 AR	68209837AA	SCREEM/WCM
1 AR	68209838AA	SCREEM/WCM, (International only)
1 AR	68209970AA	SCREEM/WCM, With Thatcham.(LS9 sales code)

REPAIR PROCEDURE

1. Replace the WCM/SCREEM, follow the remove and installation procedure per TechConnect: Vehicle Theft Security/MODULE, Sentry Key Immobilizer (SKREEM)/Removal/installation.
2. Make sure to read and follow all notes regarding key Transponders and Tire pressure sensor reprogramming.
3. Clear all codes that may have been set during the replacement procedure.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-80-28-91	Module, Scream, Replace (KK/KA) (2-Skilled)	0.5 Hrs.
08-80-28-91	Module, Scream, Replace (JK) (2-Skilled)	0.6 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------