



Service Bulletin 503

Strictly Confidential

July 2013

Affected ModelsTiger Sport ABS
VIN RangeVIN 570059 to VIN 610816
MarketsAll
SubjectOil Dipstick

Background Information

We have identified a need to replace the oil dipstick assembly on the above models. Dealers are requested to remove and replace the oil dipstick assembly.

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next service/visit to the dealership.

Identification of Affected Motorcycles

Tiger Sport ABS models listed in the VIN range above.

Warranty Claim Instructions

Fault code01264093

Repair code99503

Repair time allowance0.05 hrs

Genuine Parts Information

Genuine parts1 x T1261180, Oil Filler Cap and Dipstick

TRIUMPH

Genuine Parts Ordering Instructions.For Triumph Subsidiary and Overseas Distributor dealers using Triumph Warranty On-Line with Parts Auto Ordering Flag switched on: Order all repair parts by submitting a New Prior through the Warranty On-Line system. Entering the above repair code in a New Prior will automatically add the parts required and labour times for this Service Bulletin.

For Overseas Distributor dealers NOT using Triumph Warranty On-Line or for Overseas Distributor dealers using Triumph Warranty On-Line with Parts Auto Ordering Flag switched off: Orders should be placed using the normal parts ordering procedure.

Genuine Parts Return InstructionsDealer to retain parts for 90 days. All parts must be stored in a secure, non-public accessed area and correctly identified with a completed warranty label. Thereafter the parts must be rendered unusable prior to scrapping.

Other Instructions

Before returning the motorcycle to the customer, download the latest tune to the engine control module using the current version of the Triumph diagnostic software.

Once completed, please mark the service record book that the requirements of this bulletin have been complied with.

Replacement Procedure

Replace the oil dipstick assembly following the procedure listed below:



Warning



Throughout the following procedure, ensure that the motorcycle is stabilised and adequately supported to prevent the risk of injury from the motorcycle falling.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- The modified motorcycles can be identified by checking the 'VIN Enquiry' on Triumphonline.net.

TRIUMPH

1. Remove the oil dipstick assembly and replace with the new oil dipstick assembly. See the following illustration for identification of the old and new dipsticks.



1. **Old dipstick**
2. **New dipstick (T1261180)**

2. Check the oil level as described in the Service Manual and adjust if necessary.

Circulation

(Initial and date when read and return to central file holder)

Service Manager	Parts Manager	Sales Manager	Workshop Supervisor	Technician 1	Technician 2