
Pilling formation (small fiber knobs) on the seat covers

Topic number	LI91.18-N-048773
Version	1
Design group	91.18 Seat covers
Date	08-29-2013
Validity	Model 906
Reason for change	
Reason for block	

Complaint:

Pilling formation (small fiber knobs) on the seat cover fabric.

Cause:

Fibers loosen from the occupants' clothing (remote pilling) and/or from the fabric of the seat cover (self-pilling) and due to friction from movements, small fiber knobs form on the surface.

Remedy:

The pilling (fiber knobs) can be removed easily with a lint remover. They then no longer occur or the tendency to form pills is reduced. There is no danger of further fabric damage (chafing through).

Lint removers are commercially available. It is therefore not necessary to remove seat coverings with pilling. We recommend (e.g. during service) watching out for pilling and removing the pills with a lint remover before the customer complains about it.

This should not be claimed under warranty as it is normal wear and tear.

Attachments	
File	Designation
P91_1_.18-0240-01.jpg	1. Lint remover 2. Covering

Symptoms
Body / Seat / Seat cover / Pilling/knots

Parts


Attachments	
File	Designation
P91_1_.18-0241-01.jpg	1. Lint remover

Validity

Vehicle	Engine	Transmission
Sprinter III	*	*

Attachments

P91_1_.18-0240-01.jpg:



P91_1_.18-0241-01.jpg:

