

Reference	SSM64677
Models	LR4 / L319 Range Rover (All New) / L405 Range Rover Sport / L320
Title	5.0L V8 (AJ133) water pump improvement VINS
Category	Engine
Last modified	16-Apr-2013 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p>Issue: Coolant leak from 5.0L V8 (AJ133) water pump. Cause: A number of changes to the water pumps have been made to improve product quality. Action: Technical Bulletin LTB00352 has been released to help with water pump diagnostics, but the bulletin does not contain closing VINS because it is applicable to all vehicles fitted with the AJ133 V8 engine.</p> <p>Below is a list of VINs that can be used to monitor the improvements to the water pumps. EPQR do not need to be submitted for water pump leaks if they are before these VINS.</p> <p>Range Rover - LG120564 LR4 / Discovery 4 - LA672661 Range Rover Sport (L320) – This vehicle did not receive very latest change to water pump before production ended. Monitor from launch of New Range Rover Sport.</p>