

Reference	SSM64937
Models	Range Rover (All New) / L405
Title	Air Suspension System Compressor Operation
Category	Chassis
Last modified	26-Apr-2013 00:00:00
Symptom	304000 Suspension System
Content	<p>Issue: A customer may report a light thud type sound from the rear load space area shortly after the engine is started and normal suspension ride height achieved.</p> <p>Cause: The sound is emitted from air suspension compressor as it activates the exhaust valve to relieve static pressure loading on the delivery valve, following a height change.</p> <p>Action: A light audible thud noise may be heard from the Air compressor shortly after the engine has started and normal or selected ride height achieved. This is normal operation and not a fault of the system.</p>