

Reference	SSM64957
Models	LR2 / L359 Range Rover Evoque / L538
Title	Body panel gap/flushness issues
Category	Body
Last modified	26-Apr-2013 00:00:00
Symptom	111000 Body Panel(s)/Unibody
Content	<p><u>Issue:</u> There has been an increase in Freelander 2(LR2) / Evoque body panel gapping/ flushness warranty claims but we do not have the full details as no EPQR has been raised.</p> <p><u>Cause:</u> The cause of the increased claims is not yet known but is being investigated by JLR Body Engineering</p> <p><u>Action:</u> If any Dealer has a vehicle that requires adjustment to the Doors, Tailgate, Hood or fenders due to excessive/uneven gaps or being over/under flush please submit an EPQR. In the EPQR please attach photographs clearly showing the issue with a detailed description including measurements where possible.</p>