

Reference	SSM65077
Models	Range Rover Evoque / L538
Title	Rear Camera Inop (Low Line)
Category	Electrical
Last modified	30-Apr-2013 00:00:00
Symptom	204000 Instrumentation
	<u>Issue:</u> Rear Camera inop at low temperature
	<u>Cause:</u> Camera internal fault or water ingress into the connector
Content	<u>Action:</u> If the any of the above symptoms are encountered in the first instance check the rear camera for water ingress into the connector, If water ingress is detected replace the harness and camera, if no ingress is detected replace just the rear camera,