

Reference	SSM65577
Models	Range Rover Sport / L320 LR3 / L319 LR4 / L319
Title	Steering Column Lock Replacement
Category	Electrical
Last modified	14-May-2013 00:00:00
Symptom	205000 Electrical Accessories
Content	<p>Issue: Unable to configure a replacement Steering Column Lock with the message 'Failed to write the target identifier' displayed on Symptom Driven Diagnostics (SDD)</p> <p>Cause: New level lock introduced containing a new level of software currently not released on SDD.</p> <p>Action: The new level software will be released in a future patch file release, however in the meantime please raise a Technical Assistance case for further advice and submit an ePQR where a replacement Steering Column Lock has been fitted to a vehicle that will not complete the configuration process.</p>