

1Full key fob.wmv

Reference	SSM66357
Models	Range Rover Sport / L320 LR4 / L319 Range Rover / L322
Title	Smart key low level repair, animation of process LTB00563
Category	Electrical
Last modified	04-Jul-2013 00:00:00
Symptom	203000 Basic Electrical
Content	Issue This SSM is to support the description provided in the technical bulletin LTB00563 for smart key low level repair. Action Click on attachment to see the animation on how to carry out the repair.