

Reference	SSM66677
Models	Range Rover Sport / L320 LR4 / L319 Range Rover / L322
Title	5.0L V8 (AJ133) overheating due to incorrect coolant fill
Category	Engine
Last modified	26-Jun-2013 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p>Issue: After the engine coolant on a 5.0L V8 AJ133 engine has been partially or fully drained and filled, the customer experiences the engine overheating.</p> <p>Cause: The refill procedure has not been completed correctly, resulting in insufficient coolant in the engine.</p> <p>Action: When refilling the coolant system on AJ133 V8 make sure the TOPIx procedures are carefully followed. Please refer to the information below for the TOPIx sections:</p> <p>Range Rover (L322) 303-03C Range Rover Sport (L320) 303-03B Discovery (L319) 303-03B</p>