

EPB DTC CODES C2007-11.docx

Reference	SSM66897
Models	LR2 / L359 Range Rover Evoque / L538
Title	RR Evoque and Freelander 2: EPB DTC Codes C2007-11 and C2008-11
Category	Chassis
Last modified	11-Jul-2013 00:00:00
Symptom	302000 Parking Brake System
Content	<p>Issue: Customers have reported warning lamp illumination and Park Brake Activation / De-Activation functionality issues with related DTCs C2007-11 or C2008-11.</p> <p>Cause: JLR Engineering are continuing to investigate root cause of the issue</p> <p>Action: In order to implement a Right First Time repair, dealers are instructed to follow the attached process for root cause investigation should the above DTCs be observed. Following analysis, dealers are requested to report the causal part for the DTC flag via an EPQR.</p>