

Reference	SSM67397
Models	LR4 / L319
Title	Squeaking Noise From Steering Rack
Category	Chassis
Last modified	29-Nov-2013 00:00:00
Symptom	303000 Steering/Handling
Content	<p><u>Issue:</u> Customer may report a concern relating to a squeak noise coming from the steering column or steering rack on LR4 / Discovery 4.</p> <p><u>Cause:</u> Land Rover is currently investigating this issue to understand the root cause.</p> <p><u>Action:</u> Please follow LTB00154v2 even if vehicle is not included in the affected VIN list. From VIN: <b>AA551544</b> Once the Technical Bulletin has been followed then please feedback the results through the EPQR system quoting the Technical Bulletin number.</p>